

Strike Preparations - Jamb Electric



	Manufacturer's Product Number	Available Lip Extender	Timely Casing Filler		Fire Rated	Spacing ID	Series							Comments
			TA-8 TA-30	TA-23 TA-28 TA-28M			S	C	A	CK	AK	DE	P	
Adams Rite	7140	-01			No	B	•	YES	YES	YES	•	•	•	
	7240	-01			No	B	•	YES	YES	YES	•	•	•	
	7440	LEK7400-50	010-106099	010-206099	No	B	•	YES	YES	YES	•	•	•	
HES	4500		010-113099	010-213099	No	B	•	YES	YES	YES	•	•	•	
	RF4510		010-113099	010-213099	No	B	•	YES	YES	YES	•	•	•	
	5000	5204-1/2	010-106099	010-206099	No	B	•	YES	YES	YES	•	•	•	
	5200	5204-1/2	010-108099	010-208099	No	B	•	YES	YES	YES	•	•	•	
	7000	7000-104	010-111099	010-211099	No	B	•	YES	YES	YES	•	•	•	Use 791 Faceplate
	8000	801E	010-103099	010-203099	No	B	•	YES	YES	YES	•	•	•	
	RF8010	801E	010-103099	010-203099	No	B	•	YES	YES	YES	•	•	•	
	RF8210	801E	010-103099	010-203099	No	B	•	YES	YES	YES	•	•	•	
	8300	801E	010-103099	010-203099	Fire Rated	B	•	YES	YES	YES	•	•	•	
	8500		010-103099	010-203099	Fire Rated	B	•	YES	YES	YES	•	•	•	
	Vista V3-1	Option 1	010-103099	010-203099	No	B	•	YES	YES	YES	•	•	•	
	Vista V3-7	Option 7E	010-101099	010-201099	No	B	•	YES	YES	YES	•	•	•	
Vista V3-7E	Option 7E			No	B	•	YES	YES	YES	•	•	•		
RCI	L6514		010-109099	010-209099	No	B	•	YES	YES	YES	•	•	•	
	S6514		010-111099	010-211099	No	B	•	YES	YES	YES	•	•	•	
	F4114	LEK01	010-115099	010-215099	Fire Rated	B	•	YES	YES	YES	•	•	•	
ROFU	1402		010-104099	010-204099	No	B	•	YES	YES	YES	•	•	•	
	1507		010-102099	010-202099	No	B	•	YES	YES	YES	•	•	•	
	1702		010-104099	010-204099	No	B	•	YES	YES	YES	•	•	•	
	1802		010-104099	010-204099	No	B	•	YES	YES	YES	•	•	•	
	2402		010-105099	010-205099	No	B	•	YES	YES	YES	•	•	•	
	3402		010-104099	010-204099	No	B	•	YES	YES	YES	•	•	•	
SDC	25 Series		010-107099	010-207099	No	B	•	YES	YES	YES	•	•	•	
	45 Series		010-114099	010-214099	No	B	•	YES	YES	YES	•	•	•	
Secur-itron	UnLatch UNL-12		010-103099	010-203099	No	B	•	YES	YES	YES	•	•	•	
	UnLatch UNL-24		010-103099	010-203099	No	B	•	YES	YES	YES	•	•	•	
Trine	2012		010-112099	010-212099	No	B	•	YES	YES	YES	•	•	•	
	3234		010-102099	010-202099	No	B	•	YES	YES	YES	•	•	•	
	3478		010-102099	010-202099	No	B	•	YES	YES	YES	•	•	•	
Von Duprin	5100		010-110099	010-210099	No	B	•	YES	YES	YES	•	•	•	

STRIKES NOT AVAILABLE

Some electric strikes are not available. If the strike you would like to use is not available, please contact Timely Technical Services for explanation or alternate choices. Reasons strikes may not be available are:

1. Faceplate is larger than 4 7/8"
2. Faceplate has radius corners
3. Housing dimension exceeds the frame face on Timely frame

FIRE RATED STRIKE AVAILABILITY

Only the strikes listed above are approved for use on Timely frames. Other strikes are available as fire rated strikes but are designed to be used with frames that have a 2" space behind the frame. These strikes are not recommended for Timely frames because the wall must be cut away to make room for the strike. If any strikes are used that require the wall to be cut away, the cut out space must be caulked with intumescent caulk around the perimeter of the strike mechanism.